



# INSTRUCTION GUIDE

for the Speedy Stitcher SEWING AWL  
sews a lock stitch . . . like a machine



WHEN PASSING THREAD AROUND  
TENSION POST, BE SURE TO PASS  
IT UNDER THE THREAD RUNNING  
FROM SPOOL CHAMBER, OTHER-  
WISE, IT WILL NOT FEED FREELY

**1** DRAW OUT ENOUGH THREAD TO DO THE WORK  
PLUS ABOUT 3 INCHES FOR TOLERANCE

**2** FORCE NEEDLE THROUGH MATERIAL, DRAW SLACK  
THROUGH WITH LEFT HAND . . .

... THEN DRAW  
NEEDLE BACK

**3** FORCE NEEDLE THROUGH MATERIAL, DRAW NEEDLE  
HALF-WAY BACK WHICH  
MAKES A LOOP ON NEEDLE . . .

**4** DRAW NEEDLE OUT, WHICH BRINGS LOCK IN CENTER  
OF MATERIAL, DRAW EQUALLY HARD  
ON HANDLE AND LEFT-HAND  
THREAD

BEFORE TAKING ANOTHER STITCH, SEE THAT YOU HAVE RELEASED MORE  
THREAD BETWEEN THE NEEDLE AND MATERIAL, THAN THE LENGTH  
OF THE NEEDLE

**IMPORTANT** — Fine sewing requires Fine thread and the 130- # 4 needle.  
Both available as pictured and described below.


## Supplies for the Speedy Stitcher

### Waxed NYLON Thread (Tan)

No. 140 Coarse    No. 150 Coarse    No. 170 Fine  
No. 160 Fine



30 Yd. Skein




180 Yd. Tube



180 Yd. Tube

### Needles



No. 130 — #4



No. 130A — # 8S



No. 130B — # 8C

If these supplies  
are not available  
from your dealer  
we will be pleased  
to send you  
price list and  
order form upon  
request. Simply  
send postcard to:

Dept. S.  
**STEWART MFG. CO.**  
P.O. Box 345  
Northboro, Mass.  
01532

manufactured  
solely by the . . . .

*Stewart Manufacturing Co.*  
NORTHBORO, MASS.

PRINTED IN U.S.A.